

1/21




FIG. 1

2/21




FIG. 2




FIG. 3

3/21




FIG. 4




FIG. 4a

4/21




FIG. 5

FIG. 6a






FIG. 6b



7/21

FIG. 6C



8/21

FIG. 6d






FIG. 6e



10/21

FIG. 6f



11/21

FIG. 7a




FIG. 7b





FIG. 7C



14/21

FIG. 7d




FIG. 7e




FIG. 7f





FIG. 8



AZ cut H pol. Flat Teeth
5 freq. 24.5 - 26.5 ghz.




FIG. 9a

EL cut H pol. Flat Teeth
5 freq. 24.5 - 26.5 ghz.





FIG. 9b

19/21

FIG. 10



20/21

AZ cut H pol. Angled Teeth
5 freq. 24.5 - 26.5 ghz.




FIG. 11a

EL cut H pol. Angled Teeth
5 freq. 24.5 - 26.5 ghz.




FIG. 11b




FIG. 11c




FIG. 11d